



IMPORTANT SAFETY RECALL

NHTSA Recall 22C-002

Clek Inc. has decided that a non-compliance which relates to motor vehicle safety exists in certain Clek Olli and Ozzi Backless Booster Car Seat manufactured between January 20, 2020 and May 10, 2022.

Clek Olli booster car seats affected:

Model Name: OL12U1
Manufactured on: 2020/01/20 - 2022/05/10

Clek Ozzi booster car seats affected:

Model Name: OZ11U1
Manufactured on: 2020/03/01 - 2022/05/10



Figure 1 - Manufacturing Label Location

Description of the non-compliance:

Clek has determined that an illustration showing the vehicle belt routing diagram was not properly displayed on the booster car seats warning label.

This issue does NOT affect the ability of the child restraint system to protect the occupant in the event of a motor vehicle crash.



Figure 2 - Missing Label

Remedy of the non-compliance:

Clek will be providing all registered owners of affected car seats with a label that includes the missing illustration. It is safe to use your car seat while waiting to receive a kit to fix the issue.

Owners of affected car seats, including those who have not registered their car seat, or have moved, should contact Clek to confirm their mailing address:

- By email: olliozzilabel@clekinc.com
- By telephone: 1-866-656-2462



Figure 3 - Placement of Remedy Kit Label